



## SILAGE STRETCH FILM CHECK LIST

## **GENERAL RECOMMENDATIONS**

1) Make sure the bales are optimally pressed. The shape and mesh coverage should be considered.



In bit m

4) Cleaning and adjusting the pre-stretch rollers. In general, observe the basic machine settings or manufacturer information.



2) Bales should be wrapped with stretch film immediately after pressing, within 2 hours at the latest.





WATCH For more info:
sales@hipac.it

5) Handle the reel with care. Sharp objects can damage the film.



mechanism blade should be kept in perfect condition for a clean cut of the film after wrapping, thus avoiding long film tails.











## SILAGE STRETCH FILM CHECK LIST

## **BALES STORAGE**

10) Stack the bales immediately after wrapping, within 12 hours at the latest.

It is very important to maintain uniformity of wrapping/adhesion/ compaction.





climate change.

Н

Н

FILM APPLICATION

up to 20% of the original width.

7) It is recommended to apply at least 6 layers of film, with a 50% overlap. It is

possible to reduce the width of the film by

At least 6 layers to support the high speed and pressure performance of the latest

generation machines; at least 6 layers

to protect/preserve masses that are

too wet or too dry, excesses due to

8) The wrapping tension has to be set to a value not exceeding 70%.

The final film width, measured on the bale, should be not less than 400 mm with 500 mm film and not less than 600 mm with 750 mm film. If the film width is outside these limits, stop and check. The rollers of the prestretch unit should be cleaned regularly according to the machine instructions.



9) The height of the pre-stretch unit of the wrapping machine should be adjusted so that the center points of the bale and film reel are horizontally aligned. Thread and attach the film as per wrapper instructions.



12) Cover and protect the stack from birds. applying an anti-bird net. If necessary, keep livestock out of the stack by fencing. Check the stack regularly and repair any damage immediately. Use bales within 12 months of packing.



For more info:



11) Do not stack more than 3 bales, creating



**FILM DISPOSAL** 

Recyclabilty: Hipac silage stretch film has been designed to be 100% recyclable.